

NOW AVAILABLE!



ANNOUNCES

NEW AFM DELETE KIT FOR GM 5.3L, LC9, LH6 LMG & LY5 ENGINES

CHEVROLET 5.3-0 (325)	2007-13	Avalanche	CHEVROLET 5.3-J (325)	2007-09	Tahoe
CHEVROLET 5.3-3 (325)	2007-11	Avalanche	CHEVROLET 5.3-Q (325)	2011-14	Tahoe
CHEVROLET 5.3-7 (325)	2012-13	Avalanche	GMC 5.3-0 (325)	2007-13	Sierra 1500
CHEVROLET 5.3-J (325)	2007-09	Avalanche	GMC 5.3-3 (325)	2007-11	Sierra 1500
CHEVROLET 5.3-0 (325)	2007-13	Silverado 1500	GMC 5.3-7 (325)	2012-13	Sierra 1500
CHEVROLET 5.3-3 (325)	2007-11	Silverado 1500	GMC 5.3-J (325)	2007-09	Sierra 1500
CHEVROLET 5.3-7 (325)	2012-13	Silverado 1500	GMC 5.3-M (325)	2007-09	Sierra 1500
CHEVROLET 5.3-J (325)	2007-09	Silverado 1500	GMC 5.3-0 (325)	2007-14	Yukon
CHEVROLET 5.3-M (325)	2007-09	Silverado 1500	GMC 5.3-3 (325)	2009-10	Yukon
CHEVROLET 5.3-0 (325)	2007-14	Suburban 1500	GMC 5.3-J (325)	2007-09	Yukon
CHEVROLET 5.3-3 (325)	2007-11	Suburban 1500	GMC 5.3-0 (325)	2007-14	Yukon XL 1500
CHEVROLET 5.3-7 (325)	2012-14	Suburban 1500	GMC 5.3-3 (325)	2007-11	Yukon XL 1500
CHEVROLET 5.3-J (325)	2007-09	Suburban 1500	GMC 5.3-7 (325)	2012-14	Yukon XL 1500
CHEVROLET 5.3-0 (325)	2007-14	Tahoe	GMC 5.3-J (325)	2007-09	Yukon XL 1500
CHEVROLET 5.3-3 (325)	2009-11	Tahoe			

• Includes parts needed to disable the Active Fuel management (AFM) on GM LS 5.3 Engines

Important AFM delete Kit Notes:

- When installing a delete cam, the active fuel management lifters must be replaced using Non-Active Fuel Management Lifters.
- The valve lifter guides used in Non-Active Fuel Management engines are different from those used in Active Fuel Management engines and must be replaced when installing Non-Active Fuel Management Lifters.
- The VLOM must be replaced with a Non-Active Fuel Management Valley Cover.
- Pushrod length must be checked during installation to verify that the correct length pushrods are being used.
- The vehicle engine control module/power train control module must be reprogrammed to turn off the Active Fuel Management system in the operating software.
- **NOTE:** the engine control module software update required for this kit may not be CARB compliant.



Components must be used together

Component#	Description	Qty
MC1390	Camshaft	1
JB-2079	Valve Lifters	16
MLG100	Lifter Guides	4
MF127	Thrust Plate	1
VCT0-1000	VVT Oil Control Valve	1

Part number
MDK300
UPC: 729295151999

**** Always consult catalog listings for detailed application information****

Melling Engine Parts • P.O. Box 1188 • Jackson, MI 49204 • www.melling.com