

**NOW
AVAILABLE!**



A NEW TIMING CHAIN TENSIONER ARM

HONDA 1.5L, & 2.0L DOHC ENGINES

HONDA	1.5	(1497cc)	DOHC	L15BE	2017-22	CR-V
HONDA	1.5	(1497cc)	DOHC	L15B7	2016-21	Civic
HONDA	1.5	(1497cc)	DOHC	L15BA	2017-21	Civic
HONDA	2.0	(1996cc)	DOHC	K20C2	2018-21	Civic



Qty Required 1

Part number

BT7058

UPC: 729295317395

**** Always consult catalog listings for detailed application information****